

## C Series Identification Chart

| Joint Size | A     | B    | C    | D    | E    | F    | G     | H    | J       |
|------------|-------|------|------|------|------|------|-------|------|---------|
| 2C         | 3.12  | 0.38 | 1.31 | 0.66 | 1.17 | 2.34 | 3.34  | 0.34 | 5/16-24 |
| 3C         | 3.56  | 0.38 | 1.44 | 0.72 | 1.38 | 2.75 | 3.81  | 0.34 | 5/16-24 |
| 4C         | 4.25  | 0.38 | 1.44 | 0.72 | 1.72 | 3.44 | 4.50  | 0.34 | 5/16-24 |
| 5C         | 4.53  | 0.56 | 1.69 | 0.84 | 1.75 | 3.50 | 4.78  | 0.41 | 3/8-24  |
| 6C         | 5.53  | 0.56 | 1.69 | 0.84 | 2.25 | 4.50 | 5.84  | 0.41 | 3/8-24  |
| 7C         | 5.84  | 0.63 | 1.94 | 0.97 | 2.31 | 4.63 | 6.22  | 0.47 | 1/2-20  |
| 8C         | 8.12  | 0.63 | 1.94 | 0.97 | 3.44 | 6.88 | 8.50  | 0.47 | 1/2-20  |
| 8.5C       | 6.50  | 0.63 | 2.81 | 1.41 | 2.44 | 4.88 | 6.88  | 0.53 | 1/2-20  |
| 9C         | 8.25  | 0.63 | 2.81 | 1.41 | 3.31 | 6.63 | 8.63  | 0.53 | 1/2-20  |
| 10C        | 3.38  | 1.00 | 3.63 | 1.81 | 2.25 | 6.50 | 8.88  | 0.53 | 5/8-18  |
| 12C        | 11.38 | 1.00 | 3.63 | 1.81 | 4.75 | 9.50 | 11.88 | 0.53 | 5/8-18  |

